



**SDR 35 GASKET REPAIR COUPLING**

10X10

**PLASTIC TRENDS**  
.COM

56400 Mound Road, Shelby Township, MI 48316  
Phone (586) 781-2700 Fax (586) 781-0888

PRINTED COPIES ARE FOR REFERENCE ONLY

DATE 6/2/2006 BY KJS

G6210.D01